ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

# BBMP ENGINEERING DEPARTMENT

## Road History Data Sheet

### General

| Zone | Ward No. | Ward Name |
|---|---|---|
| YELAHANKA | 9 | Vidyaranyapura |

| Street ID | Street Name | Significant Landmark |
|---|---|---|
| W0675, W0681, W0683, W0411, W0401, W0805, W0514, W | NA | Vidyaranyapura |

| Segment No. | Total Length (m) |
|---|---|
| 9/C-W0675/S111805 | 601.23 |

**Segment Details**

| Seg No. | Length (m) | Start Coordinates | | End Coordinates | | From | To |
|---|---|---|---|---|---|---|---|
| 1 | 113.32 | 77.571392 | 13.063806 | 77.570743 | 13.063195 | LG Enclave | 10th main |
| 2 | 45.21 | 77.561980 | 13.070521 | 77.562393 | 13.070466 | Basavasamithi | 1st A Cross |
| 3 | 197.29 | 77.560872 | 13.069745 | 77.561969 | 13.070510 | Basavasamithi | 1st Cross |
| 4 | 77.63 | 77.561395 | 13.070581 | 77.561264 | 13.069891 | Basavasamithi | 2nd C ross |
| 5 | 78.42 | 77.561682 | 13.070539 | 77.561540 | 13.069844 | Basavasamithi | 2nd B Cross |
| 6 | 89.36 | 77.566791 | 13.064408 | 77.567000 | 13.065189 | Kempegowda nagara | cross road |

### Work Details

**History of Road / Lane / Circles**

| Name of the Work | Sanctioned Estimated Amount (Rs.) | Sanctioned Year |
|---|---|---|
| Improvements to roads, drain and drilling borewells in ward no. 09, 10 & 11 Vidyaranyapura sub division. | 30500000 | 2015-16 |

| Year | Type of Work | Other Work Type |
|---|---|---|
| 2015 - 2016 | Others | Road and drain |

| Tender | Work Details | Job No. / Work Code |
|---|---|---|
| Tender | Road and drain | 009-16-000027 |

| Work Order No. | Work Order Date | Period of Extention |
|---|---|---|
| BBMP/EE/BTP/WO/42/2018-19 | 19/07/2018 | |

| Defect Liability Period From | Defect Liability Period To | Multiple road involved with the same Job No/ Work Code # |
|---|---|---|
| 26/07/2018 | 26/07/2019 | No |

### Contractor Details

| Name of Contractor | Contractor Reg No (BBMP/PWD) | Expenditure Booked \ Released (Rs) |
|---|---|---|
| Alankar | | 0.00 |

Zone: YELAHANKA Ward No: 9 Ward Name: Vidyaranyapura Street ID: W0675, W0681, W0683, W0411,

Assistant Executive Engineer
Vidyaranyapura Sub Division
BBMP, Bangalore - 97

Scanned by CamScanner

| No. | E-Mail ID |
|---|---|
| 252997 | |

## ld Inspection Details

| Number of Trees | Any Other Information | Name |
|---|---|---|
| 0 | | krishnappa |

| Date of Inspection | Remarks |
|---|---|
| 26/07/2018 | |

| Category | Image | Photo Remark |
|---|---|---|
| Road Condition | | This photo seems out of range. |
| Road Condition | | This photo seems out of range. |
| Road Condition | | This photo seems out of range. |
| Road Condition | | This photo seems out of range. |
| Road Condition | | This photo seems out of range. |
| Road Condition | | This photo seems out of range. |

## Remarks

| Designation | Approver Name | Date | Target Date | Remark |
|---|---|---|---|---|
| CE | R.L.Parameshwaraiah | 30/07/2018 | 25/08/2018 | As proposed |
| SE | Vasu K M | 28/07/2018 | 25/08/2018 | Completed |
| EE | mohan das | 27/07/2018 | 25/08/2018 | verified |
| AEE | shivakumar | 26/07/2018 | 25/08/2018 | verified |
| AE | Krishnappa | 26/07/2018 | 25/08/2018 | Mobile verification is done |

Zone: YELAHANKA Ward No: 9 Ward Name: Vidyaranyapura Street ID: W0675, W0681, W0683, W0411,

AE

Assistant Executive Engineer
Vidyaranyapura Sub Division
BBMP, Bangalore - 97

Scanned by CamScanner

| | | | | |
|---|---|---|---|---|
| | Krishnappa | 26/07/2018 | 25/08/2018 | Forwarded |

AE

Zone: YELAHANKA

Ward No: 9

Ward Name: Vidyaranyapura

Street ID: W0675, W0681, W0683, W0411,

Assistant Executive Engineer
Vidyaranyapura Sub Division
BBMP, Bangalore - 97

Scanned by CamScanner